



.....















$$_2 = ($$



$$I_{CINRMS} = I_{OUT} \sqrt{\frac{V_{OUT}}{V_{IN}} \left(1 - \frac{V_{OUT}}{V_{IN}}\right)}$$

$$I_{CINRMS} = 0.5 I_{OUT}$$

$$\Delta V_{IN} = \frac{I_{OUT}}{f_{SW} C_{IN}} \frac{V_{OUT}}{V_{IN}}$$







	SYMBOL	MIN	NOM	MAX
TOTAL THICKNESS	A	—	—	1.75
STAND OFF	A1	0.05	0.125	0.20
MOLD TOTAL THICKNESS	A2	1.30	1.40	1.60
LEAD WIDTH	b	0.31	—	0.53
LEAD WIDTH	b1	0.30	0.40	0.50
LEAD THICKNESS	c	0.20	—	0.24
LEAD THICKNESS	c1	0.19	0.203	0.21
MOLD LENGTH	D	4.80	4.90	5.00
MOLD WIDTH	E1	3.80	3.90	4.00
LEAD SPAN	E	5.80	6.00	6.20
LEAD RITCH	F	—	1.27	1.50

EXPOSED PAD SIZE	X	J	2.15	2.30	2.45
	Y	K	2.25	2.40	2.55
LEAD LENGTH	L1	1.05 REF			
LEAD SOLE LENGTH	L	0.40	0.60	0.80	
LEAD FORM ANGLE	θ	0°	—	8°	

